

After performing the above actions, inform defects found on the ATL or on additional work as for example:

- The number of clogged drains holes
- The matter who is out
- Etc...

**OPERATIONAL IMPACT**

Nil

**CORRECTIVE ACTION**

- A new standard of pitot probe is available PN: C16195BA. The installation of this PN is in progress by attrition on the fleet.

The new pitot probe corrects the problems with enhanced water trap and relocated drain holes.

**END**