

# A project of Volunteers in Asia

Report on Training of District Extensionists

Published by:

ITDG

## Available from:

ITDG Stoves Programme
Myson House
Railway Terrace
Rugby CV21 3HT
UNITED KINGDOM
Reproduced by permission.

Reproduction of this microfiche document in any form is subject to the same restrictions as those of the original document.

### REPORT ON TRAINING OF

DISTRICT EXTENSIONISTS

### SARVODAYA/CEB STOVE PROGRAMME

Kandy, Sri Lanka

9 - 23 August, 1985

## TABLE OF CONTENTS

1.	Abst	ract	•	•	•	•	•	•	•	•	•	2
2.	The	Cont	ext	•	•	•	•		•	•	•	2
3.	Goal	ls .	•	•	•		•	•	•	•		3
4.	The	Prog	ramme	<u> </u>								
		Wee	k 1	•	÷		•	•	•	•	•	3
		Wee	k 2		•	•	•	•	•	•	•	3
5.	Eval	luati	on .	•	·		•	•	•	•	•	4
6.	Foll	lowup			atna	משות	Die	trict	~			
			CEB/I	Energ	y Un	īt	•	•				6
			unaga			Dis	tric	ts				
			Sarvo	odaya	. •	•	•	•	•	•	•	9
Appe	endio	cies										
App.	. 1	Trai	ning	Time	Tab	le	•	•	•	•	•	11
App.	. 2	Clay	and	Cera	mic	Lect	ure 1	Notes	•	•	•	1.3
App.	. 3	Work	ing v	vith	Pott	ers	•	•	•	•	•	20
App.	. 4	Gett	ing t	he M	lea <b>s</b> u	reme	nts :	Right	-			
			ustra				empl	ates		•		26
App.	. 5	Obse	rvat	ion S	heet	. •	•	•	•	•	•	29
App.		Foll	owup	Lect	ure	Note	s.	•	•	•		31
App.			owup			•	•	•	•	•	•	33
App.			for						•	•	•	37
App.			tion: psis					Evalu	atio	on	•	44
- 15 E			luati					urse	•	•		47

### ABSTRACT

The two-week course included 10 students with all levels of stove experience from both CEB and Sarvodaya. The training goals were to impart sufficient technical background so the students could conduct supervision of all stage of production and evaluation of the 2-pot chimneyless installed "Sarvodaya" stove. Despite this ambitious objective, the training seemed to be successful in giving sufficient understanding in several key technical areas.

An additional two weeks was devoted to each of the CEB and Sarvodaya stove programmes for followup on their trainees.

Due to the brevity of the course, special care will be required by management to determine what each student's abilities are, and where additional training is required.

#### THE CONTEXT

The training was conducted by Mr. Lamasena of Sarvodaya and John Selker and Laurie Childers of ITDG, with lecture support by Mr. Bandara and Mr. Amerasekera of CEB Energy Unit, and John Loose of ITDG. Additionally, an introductory speech was given by Prof. K. K. Y. W. Perera, Secretary of the Ministry of Power and Energy, and a concluding speech was given by Mr. Sisira Navaratne, Division Field Officer for Sarvodaya.

Most activities took place at Sarvodaya District Center, Palletalawinna, Kandy. A small classroom was constructed just prior to the training, and the practice installations took place nearby. Several days were spent in nearby Wallala at a potter's house for demonstrations and practice in the construction of the pottery liners.

The most important factor in determining the focus of the training was the students' diverse backgrounds. Of the six students from the CEB, three were newly recruited staff who had never worked with ceramics or stoves; one had installed over 50 stoves, and two were potters with extensive experience. The four Sarvodaya students included two experienced stove installers, one stove producing potter, and one village health worker.

Language was a significant obstacle in the training. None of the students were fluent in English, so all lessons from the ITDG staff needed to be translated into Sinhalese. A Sarvodaya translator, Mr. Charles, was hired for this. Given the obscurity of the fields of stoves and ceramics, adequate translation was difficult to obtain. None of the Sinhalese lectures were fully translated for the ITDG staff.

#### **GOALS**

This training was directed towards resolving the key technical bottlenecks which have historically held up stove dissemination in Sri Lanka. Three areas were selected as particularly crucial and appropriate for this training: skills in working with potters, technical troubleshooting and evaluation, and understanding the issues and activities important to successful stove dissemination.

THE PROGRAMME (See Appendix 1, the Time Table)

#### Week 1

After introductions, and practical cooking on the 2 - pot stoves, the entire first week of the training was devoted to production issues surrounding the ceramic stove liner. The first day on ceramics was largely basic pottery theory background. The students were guided by first learning the key descriptive vocabulary of ceramics. The vocabulary was then placed into perspective by leading a discussion through the steps of production of a ceramic stove liner.

The next two days were spent working with a local stove-producing potter. After complete demonstrations by the potter, each student made one liner. The work was monitored by Mr. Lamasena and Mr. Bandara. Techniques of throwing, coiling, and slab rolling were demonstrated, but the students were directed to use coils for reasons of simplicity. In this society where the potters are of very low social standard, it was critical to get all of the students to work with the potters and with clay to break any social barriers gently but thoroughly.

On Friday of the first week, the overall subject of working with potters was discussed. Special note was made of the richness of the local pottery traditions, the expected stages in training a potter to produce the pottery liner, and the economics of pottery production. As three of the student were potters, the discussion produced particularly successful results. See Appendicies 2, 3, and 4 for lecture notes on ceramics, notes on working with potters, and pictoral demonstration of the use of templates.

### Week 2

The second week was devoted to 3 subjects: stove evaluation; followup and dissemination; and installation practicals.

The stove evaluation section was aimed at enabling students to differentiate between serious and cosmetic errors in the liner and the completed stove. Each group of 2 - 3 students made measurements and observations of 2 stoves (see Appendix 5). Through this exercise, the students discussed and committed themselves on paper to judgements regarding each stove's strengths and faults. Subsequently each group conducted a water boiling test on both of the stoves. During the test

the students wrote qualitative observations about the stove's performance regarding expected efficiency, usability, and safety. The results of the tests were displayed on the chalk board for interpretation.

The next day the group was given an opportunity to discuss their findings. We were extremely gratified to find that each group had identified the key issues with each stove. Often their final conclusions differed from the initial observations. This exercise was successful in giving students the tools for distinguishing between good and bad stoves and liners.

The subject of followup was put into perspective by having both the CEB and Sarvodaya describe their field programmes, with focus on the role of District Extension Coordinators in dissemination. In both approaches, followup was a key responsibility for the extension coordinator. After a brief lecture further explaining the role of followup, each student was given 2 followup forms (see appendicies 6 and 7). The form was discussed line by line, and general questioning courtesy and methods were discussed. Each student went to two houses which had improved stoves to make observations. To summarise the study of followup, each student acted through a brief report of observations both to his "supervisor" and the installer (which for these stoves was Mr. Bandara). Students were directed to discriminate between the general experience of the field visit and the particular information which would be valuable to the other parties.

In the later class sessions stove installation was practiced and other issues were discussed. The course was concluded with a comprehensive test and course evaluation (see appendicies 8 and 9).

### **EVALUATION**

Overall, the training was quite successful. It went more smoothly than expected and the students expressed appreciation for what they learned. The content was dense, and every effort was made to distribute translated lecture notes and handouts to assist the comprehension and memory of the trainees. The training received excellent support from all concerned parties: Sarvodaya, CEB, and ITDG. Mr. Lamasena's preparatory work was of great help throughout the course.

As always, there were faults with the training that are worth considering with regard to future trainings of this sort.

1. The training programme was over-ambitious. Too many subjects were to be covered in a short time. As a result, there was far too little time for classroom discussion which is essential for clarifying ideas and reading the actual level of comprehension of the students. This problem was recognised in the days prior to the training, but those in charge of the training (Lamasena, Selker, Childers) chose not to substantially alter the course content due to their limited planning inputs. In future trainings, priorities should be limited to those

subjects which can be treated thoroughly - this one had three priority subjects, and that was two too many. Within each subject, we included too much information for students to absorb. Short topics such as chimneys and in-depth technical ceramic detail seemed worthwhile for setting the context of the main points. However, the sense of what was essential gct lost, partly in the translation and partly due to the sheer volume of information. We underestimated the mental strain involved in absorbing so many ideas. The diverse levels of experience amongst the trainees complicated this matter. We chose to direct the level of information toward those most likely to use it, i. e. the more knowledgeable.

- 2. Inadequate translation severely hampered the communication of ideas in lectures. The training planners anticipated that translation would <u>not</u> be necessary. Once the training was underway it was seen that a full- time translator was necessary, and one was hired. However, the technical vocabulary and esoteric concepts caused problems, particularly with the over-enthusiastic translator who sometimes jumped ahead of the lecturer he was translating for and gave exactly the opposite meaning. Although most of these mistakes were caught, this caused much confusion for the class. Also, many of the technical ceramic words have no direct parallel in Sinhalese, and succeeding lecturers used different words for given definitions. Although both of the main Sinhalese-English speakers were specially briefed on the difficult vocabulary, ideas were made substantially more confusing because of the partial knowledge of the translator. More time allocated to the selection and preparation of the translator could have helped to mitigate this problem.
- 3. While Sarvodaya District Center was on the whole an excellent site for such a training, there were several drawbacks to our exact location. The room is nearby the metal and wood shops, and their machinery was quite noisy most of the day. Also, the room itself was too small for so many people. Additionally, there were some complaints of a different nature from the students about being required to attend Sarvodaya's Family Gatherings every evening, as these occupied most of the time students had for relaxation and study.

Feedback from the students at the close of the training was overall positive. Primarily, they felt that the training was well organised, the amount of time and amount of work were fine, but that there was too much theory in relation to practical work, and too little time for classroom discussion. They would have liked more time for practical work with producing the stove liner and installation. A synopsis of (translated) evaluation responses is given in Appendix 10.

#### FOLLOWUP REPORT

Visit to Hambantota and Ratnapura Districts

CEB/Energy Unit - Trained Pottery Liner Producers

Sept. 1985

By Laurie Childers, ITDG Stoves Project

#### Hambantota District

Mr. Ranasinghe, Coordinating Officer

Mr. K. K. Ariyasena, trainee extensionist

### Ratnapura District

Mr. K. D. Wijeratna, Coordinating Officer

Mr. H. Dayananda, trainee extensionist

Mr. Bandara, Trainer for CEB/Energy Unit Stove Programme

### SUMMARY

The training of potters in Hambantota and Ratnapura Districts is proceeding remarkably well. This is due mostly to the competence of Mr. Bandara, the trainer, and to the support system of the CEB and District Government of Sri Lanka infrastructure. It is recommended that the present training and followup system continue, maintaining careful quality control. Financial arrangements must be clarified so that potters get paid promptly.

#### **ACTIVITIES**

One week was spent in Hambantota District with Mr. Ranasinghe. Initially a discussion was held with the Assistant Director of NORAD's IRDP, which funds the project. We visited approximately 34 pottery households is 6 divisions, and talked with 5 Assistant Government Agents (responsible for collecting and distributing stoves) and one Special Service Officer (responsible for coordinating installers and householders). Unfortunately we spent only 2 hours with Mr. Ariyasena, the trainee.

In Ratnapura District, the two pottery villages which are producing stoves were visited: Kallekolonne (18 families) and Damana (5 families) and their headmen. One day was spent in each village. Mr. Bandara did some training of one of the Damana potters, and the author conducted a demonstration of the the score and slip method of making strong joints. Mr. Dayananda was present for both days, and Mr. Wijeratne for one day.

At each pottery site, we evaluated the quality of stoves produced and discussed the dimensions with the potters. We asked the potters if they had any problems with cracking and discussed possible solutions to those problems with them.

### **OBSERVATIONS**

- 1. The quantity and quality of training done by Mr. Bandara far exceeded the author's expectations. Of the nearly 60 potters visited, only a handful were producing imperfect stoves, and those had only marginally incorrect dimensions. Mr. Bandara's manner is that of precision, patience, and persistence. Around most potter's houses is a line of pottery fireboxes being used as flowerpots. The potters would laugh and say, "These were from my training period." The demands for precision necessary in the early stages have more than paid off in the obvious quality of liners produced.
- 2. Overall the level of pottery skills is quite high, particularly in Ratnapura, with several outstanding pottery households in both districts. Some potters had trained themselves to build the liners. In Hambantota, the clay mixtures and construction techniques varied even amongst potters living right next door to each other. Use of any particular technique (coil or wheel methods) did not seem to affect the final quality.

- 3. Most potters seemed to have one or two very minor problems. These include:
  - a) cracking of liners during the firing, especially those loaded on the bottom of the kiln;
  - b) cracking of joints due to faulty construction;
  - c) potholes too large or small (templates not always used);
  - d) potrests too thick, and/or not strongly attached;
  - e) airholes too large and/or too high;
  - f) off-round firebox potholes.

Potters in Ranna, Hambantota District, were the only ones who complained about the loss of liners due to cracking during firing. Other potters said that they actually had less loss of liners than of traditional pots, which are much thinner and break more easily. Potters were happy to make the stoves for Rs. 15 each, taking the average 10% breakage at a loss.

- 4. The worst problem encountered regards the organisation of finances. In Hambantota District, there is often a 3 week delay in paying potters. Most potters are quite poor and live hand-to-mouth. Aside from being unfair to the potters, it will soon discourage them from producing stoves.
- 5. There is an enormous amount of transport for the liners required using the present dissemination method.

#### RECOMMENDATIONS

- 1. Continue close contact with potters, giving attention to quality control and problem solving. It seems to be fairly easy for potters to make minor mistakes that they haven't been making previously, such as raising the airhole too high, altering the door shape or size, etc. Templates may need to be refined and redistributed. Also, the potrests on the second potholes should be about 1 cm thick only. This small detail greatly affects the fuel consumption of the stove.
- 2. When liners are being purchased, they should be carefully screened for cracks that have been "repaired." Many potters tend to smear clay into cracks just prior to firing, but this is a disguise and <u>not</u> a repair. These cracks are often in the joints.
- 3. By the middle of the third year of the project (1987), attention should be given to switching over to a sustainable marketing system. Methods of transport and quality control will have to be devised. It will be necessary for the public to have a sense of what is a high-quality stove. The Energy Unit should award a "seal of approval" to those potters who are making particularly precise, high-quality stove liners. This could be in the form of a stamp that they use to mark their ceramics, and/or a certificate that can be displayed at their workshop or in retail markets.

#### FOLLOWUP REPORT

# Kurunagala and Kandy Districts Sarvodaya Extension Workers

Sept. 1985

### By John Selker, ITDG Stoves Project

1. Mr. Lamasena of Sarvodaya and myself visited Mr. Dammith, trainee, for 3 days at his site in the Kurunagala District of Sri Lanka. We assisted him in his first 3 working trips to potters in his area. He seems confident and well-prepared. Since a stove installer's training was carried out in the area 1 year ago, the demand for improved stoves is already established.

In our discussions, we focused on how Mr. Dammith could make his stove work as self-supporting as possible. The Kandy District Center had already supplied 30 stove liners, and an account of almost Rs. 700 has been established through the installation of these stoves. This site was seen to be an ideal place to investigate ways to smoothly transfer the improved stove technology within the Sarvodaya system.

From this perspective we left Mr. Dammith with a strategy for starting his stove project. We encouraged him to write a proposal for covering his Rs. 300 per month tramsportation expenses to the District Center. From later conversations with Mr. Amerasekera of the C. E. B., we believe additional support will be forthcoming from the C. E. B. for Mr. Dammith's work.

2. Mr. Lamasena, Steve Raggett, Laurie Childers, and myself visited trainee Mr. Somaratna for 1 day at his site in Kandy District. His work with stoves predates the training by two years. He was working with a potter who was making high quality stoves, and Mr. Somaratna had a team of installers actively working. By and large we were quite impressed by Mr. Somaratna's ingenuity and perserverence.

The economic side of his efforts were particularly interesting. He purchased liners from the potter for Rs. 15 each, including delivery. He then sold the liners to the installers for Rs. 30 each. The installers in turn sold the completed stove to the households for Rs. 45.

Only one serious problem was observed. Mr. Somaratna had decided that two sizes of stoves were required in his area, and instructed the potter to make a 2/3 size version. This smaller stove was observed in operation in homes and was seen to be unacceptable. The shorter firebox quenches combustion, cooling

the flame; making smoke, and leading to thick buildups of creosote in the second pothole. Mr. Somaratna was shown these problems, and understood he needed to rebuild the smaller stoves and discontinue their production. He can order stove liners with potholes of a smaller diameter, but the fireboxes must be of the same height as the regular firebox.

## TIMETABLE

WEEK 1	<u>L</u>	LECTURERS		
Day 1	- Monday			
a.m.	Introduction	Secretary,		
	- people - description of SSM & CEB programs	Min. of Power & Energ Prof. K. Perera		
	Why the stove is designed like it is			
	- technical aspects - Socio economic aspects	Lamasena Bandara		
p.m.	How the stove works (demonstration - cooking lunch)	Lamasena		
	Design and effect of changes on stove performance	J. Loose		
Day 2	- Tuesday			
	Pottery materials: clay, clay preparation	L. Childers		
	Introduction to making stoves			
	forming and joining drying and shrinkage firing theory (demonstrations and theory)			
Day 3	- Wednesday			
a.m.	Visit to pottery at Wallalla	Lamasena		
	Demonstrations: making coils coiling firebox coiling tunnel throwing second pot, adding knobs use of templates assembly of tunnel and door			
p.m.	Making stove parts (training by potters in the group)	Supervised by Lamasena <u>or</u> Bandara		
Day 4	- Thursday			
a.m.	Assembly of stove parts	L. Childers		
p.m.	Reviewing construction	L. Childers		
Day 5	- Friday			
a.m.	Training potters and firing - quality control - problem solving - clay modification and improvements - economics and breakage	J. Selker L. Childers		
	- tradition and science			
•		cont to		
	•	cont'd		

WEEK 2		LECTURERS
Day 6 -	Monday	
a.m.	Evaluation of stoves/testing	John Selker
	Qualitive observation Measurement of ciritcal dimensions	
p.m.	Comparative cooking tests	
Day 7 -	Tuesday	
a.m.	Summary of stove evaluation	John Selker
	Intro to follow up	Ms. Harshini Navaratne Sarvodaya Dist. Coordinator
		Mr. Lamasena, Overall Coordinator, CEB Energy Unit, Stoves
p.m.	Follow up at local homes	Selker/Lamasena/Ban- dara
Day 8 -	Wednesday	
a.m.	Follow up summary	John Selker
	Chimneys/introduction to installation	John Loose/Lamasena
p.m.	Practice Installation at Training Site	Lamasena/Bandara
Day 9 -	Thursday	
	Practical installation at local homes	Lamasena/Bandara
Evening	- slide show	Selker/Childers
Day 10	- Friday	
a.m.	Review	Lamasena
	Test	Bandara
p.m.	Evaluation	Childers
	Closing	J. Loose Sisira Navaratne

### Appendix 2

CLAY AND CERAMIC LECTURE HOTES Laurie Childers ITDG

Sri Lanka CTB/Sarvodaya Training Doy 2 13 August 1985

Today we want to increase your understanding of clay, what it is and what happens to it between taking it out of the ground and becoming a finished stove liners

### What is clay?

The term clay refers to a certain particle size of a soil mineral.

Clay comes from weathered rocks. When rocks are exposed to sunshine, to heat and cold, to rain and ice, they decompose, or break down into small particles. This is usually a very slaw process, and some rocks take much longer to decompose than others. Some rocks break up rather easily, and get carried downhill by glaciers or streams. The finest particles get carried the farthest, they are often dropped only when the river spreads out over a flood plain and slaws down. Many layers of these tiny particles become clay deposits. (Some clays are formed differently: the rock decomposes inplace. These clays are usually very white.)

Clay is defined as a particle size which measures 10 microns or less in size. That means that 100 of the largest clay particles, side by side, would measure only one millimeter across. Silt is the next largest particle size: 40 of the largest silt particles measure one millimeter across. Sand is the next largest particle size: fine sand measures up to one third of a millimeter across.

## Why does clay stick together?



shape of clay particles

chemical structure of clay (simplified)


Clay particles are hydrated, that is, they are chemically bound to water. Even after clay has dried in the sun, there is still water between the the clay particles. This bonded water sticks to other water, and so the particles of wet clay are both attached and lubricated by the water between them. The clay particles slide apart or closer together as the clay is pressed and formed.

Smaller particles of clay have more surface area, and can hold more water in between them relative to larger clay particles. Clay that is very sticky has small particles of clay.

The ability to stick together, and to be formed without cracking, is called <u>PLASTICITY</u>. If clay can be easily shaped, we say it is highly plastic. If it breaks when coiling around your finger, it is not very plastic. Plastic clay is flexible due to having a good mix of particle sizes. Plastic clay has some very fine (small) clay particles. But very fine clay, all by itself, is too sticky to work with.



non-plastic clay




plastic clay One of the reasons we blend different clays together to make pots and stove liners is to get good plasticity. This enables the clay to be formed without cracking, and also dry without cracking. (The clay grips and holds onto itself.)

Plasticity also increases with ageing the clay. In many parts of the world, potters mix clay weeks or months before they use it. In China, potters work with porcelain, a non-plastic clay. They mix clay for their grandchildren and use clay made by their grandparents.

## What happens during drying?

After a clay piece has been formed, it is left to dry. While drying, most of the water between the particles of clay evaporates into the air. Just like drying clothes, this happens faster when the air is warm and dry and the piece is in the sum. However, with clay pieces, it is very important that they dry evenly - from side to side, top to bottom, and inside and out. Careful drying is important because as the water between the clay particles evaporates, the clay particles more closer together. This results in the piece shrinking in size. If one part of the pot or stove liner dries faster than another part, then it shrinks more and cracks away from the rest.

Thinner parts dry faster than thicker parts, so it is important that the clay walls be of all the same thickness. The edges of any pieces should be slightly thicker because they dry faster.



Traditional folk potters usually add materials with large particle sizes to the clay mix to help the pieces dry evenly. The relatively large grains of sand, mica, or "grog" (crushed fired clay) do not shrink. They also allow a path for water between particle inside the clay wall to pass toward the ouside of the clay wall and evaporate. The tiny holes in such clays make them porous, we say they have high porosity. (A sponge is another example of porosity.) Very plastic clays, all by themselves, tend to warp and crack (unless they are very slowly and very carefully dried).

sand grog (crushed rottery)

mica (a soft rock that has thin layered crystals)



The clay is actually strongest during the <u>leatherhard</u> drying stage. This is when the clay is stiff and feels like leather - not quite wet and not quite dry. It is difficult to deform or pull apart. When clay is very dry (much lighter in color), it easily chips when bumped because there is not enough water to hold the particles together.

Clay and ceramic lecture note, page 3

## What happens when the clay is fired?

During the firing process, the clay changes to ceramic. After proper firing, the piece cannot be dissolved into clay again. There are several stages of firing which are important to to look at in respect to firing pottery stove liners.


At 100° C, water is boiled out of the clay. Between 100° and 200° C, water finally escapes from between the timiest clay particles. When water turns to steam, it expands greatly. Therefore the early stages of firing must be very slow so that the steam does not form inside the clay walls. Steam can cause little explosions or cracks in the clay pieces.

At 573° C quartz inversion occurs. This is marked by a structural expansion of the free silica in the clay body. At temperatures below 573° C, the silica crystals are in a cramped state. At 573° C, it suddenly stretches out into a symmetrical shape that is 1% larger in size. It stays in this state until it cools below 573° C, when it suddenly inverts back to the cramped state and shrinks 1% in size. In the same way that thin parts of a piece might dry too fast, there can be problems with thin parts during this stage of the firing. The kiln should heat slowly during quartz inversion so that all parts of the ceramic pieces reach 573° C at the same time. Otherwise the thinner parts may crack off.

Upon reachin the temperature range between 600° and 700° C, the clay will no longer dissolve in water. In fact, it is no longer clay. It is now ceramic, but has yet to develop a good ceramic bond. It is weaker now than when it was dry clay.

Between 850° and 950° C, the solid particles begin to sinter. Sintering is what gives ceramic pieces fired strength. The particles stay solid but the surfaces begin to "weld" together, much like iron pieces weld together without melting. Other minerals in the clay, such as potassium or iron, will help encourage sintering. After sintering, the particles are no longer separate, but have joined into one very porous piece.

At temperatures above 950° C, the ceramic begins to <u>vitrify</u>. It becomes more and more like glass. And, like glass it is unsuitable for stoves. The particles melt together and fill the pores between them. (The ceramic shrinks significantly as it vitrifies.) While stoves are used for cooking, parts of it receive enough heat to expand significantly. Low-fired (900° C) porous stoves can absorb the shock of thermal expansion because of the spaces between the "particles." High-fired ceramic has no room for uneven thermal expansion, and the firebox is likely to crack.



# තෙත මැට් සහ පිලිස්සුනු මැට් පිළිබඳ දේශන සටහන්

මි.ල.වී.ම. හා සර්චෝදය ඒකාබද්ධ දර උලුත් පිළිඹුඳ පුහුනුව සර්චෝදය දිස්තුක් මටහස්ථාතය 1985.08.13 වෙති දිත ලූරි චිල්ඩර්ස් මහක්මිය අයි.ඊ.ඩී.පී. අද අපිට මැටී පිළිබඳ සබහේ දැනුම චර්ධතය කිරීමට අවශා වේ. මැටී යනු කුමක්ද? වසේම එය පොලවෙත් ගැනීමටත් ලිපක් සෘදා අවසත් කිරීමත් අතර, වෙතස කුමක්ද දැතගත යුසුය. මැටී යනු කුමක්ද?

මැට් බණිප දුවාවල තිබෙන එක්තරා වර්ගයක කුඩා අිංශු වශයෙන් සඳහන්තල හැක. මැට් ලැබෙන්නේ පරිත වලට කාලගුණය ඔලපැමති. පරිත හිරු එලියට, සේකත්වයට, ස්තුලට, වැස්සට අස්ස්වල ඔලපෑම තිසා එහි කියාකාරිත්වය කරනකොටගෙන යුතා කුඩා කෑලි වලට තැබී යටි. මෙය යුතා හෙම්හිට සිදුවන්නකි. එසේම සමහර පරිවත වෙතත් චරිත වලට වඩා මෙසේ සු සිදුවීමට කාලයක් ගතවේ. සමහර පරිත යුතා පහසුවෙන් මෙසේ කැඩේ. යුත් පසුව ඒවා චණ්ඩ තිසා තිමිත වලට ගලායයි. ඒවායේ හෝසු කොටස් අෑතට ගලායයි. ඒවා ගංවතුර ගලන කාලයට ගඟෙහි දෙපස මිදෙන්නට පටත් ගත්. මෙසේ කිපවතාවක් මිදෙන විට එම තට්ටු මෑට් බවට පත්වේ. සමහර මැට් වර්ග වෙතත් වෙතත් කුම වලට ගැඩගැසේ. පරිත වෙතත් කුම වලට දිවායයි. ඒවා සාමාතුවටෙන් සුදුජාවය.

මැට් සාමාතායෙන් මයිකුදු 10 ව හෝ අවස් වඩා කුඩා පුමාසයේ අදේ වලට ශතහැකිය. මෙහි අදහස වනුයේවය පැත්තෙන් පැත්තව සියවාරයක් විශාල මැට් අදේ මිලි මීටර් 1 ක් පමණ මැතිය හැකිය. එලඟට විශාල අදේව තම් මීදෙත මැටීය. 40 වාරයක් විශාල මෙම අදේවක් හරහට මිලි මටුරයක්වේ. එලඟ එශීය තම් වැලිය. ශූතා හොඳ වැලිකැටයක් මිලි මීට්රයකින් 1/3 කි.

# <u>ඇයි මැටි එකට ඇලෙන ගතියකින් යුක්ත වන්තේ?: –</u>



මැටි අංශුවල නැඩය


මැට්වල රසායනික සංයුතිය

මැට්ටළ රසායනික වනුහය සාමාතනයෙන් මැට් අදෙවක ජලය ඇත. එහි අදහස ඒවා රසායනික වශයෙන් ජලයෙන් බණ්දී.ඇත. මැට් අව්වෙන් වැස් ඇතන් ඒවාතුල ජලය ඇත. ඒ නිසා ජලය අතින් කොටස් වලට එකතු වේ. එතිසා මෙම අඥ හෙත මැට් එකට ඇලෙන ගතියෙන් හා ලිස්සන ගතියනින් යුක්ත වේ. මිතිසා මැට් එකට හැඩගන්වන වීට හෝ තකු කරන වීට ඇලේ.

ශූතා කුඩා මැටි අ•ෑඵල මුදුතන බොහෝ ඇත. ඒවායේ වීශාල කෑලි වලට වඩා ජලය උරාගත්තා සිදුරු ඇත. ශූතා හොඳට ඇලෙන මැටිවල ශූතා කුඩා මැටි අ•ඥ ඇත.

අදෙත සුම් ශතිය යනු මැටීවල ඇලෙන ගතිය හා එය තොකැඩි නවායැනිව – ට හැකිවීම. මැට් පහසුවෙන් හැඩ ගත්වා ගැනමට නම් අපි එය හොඳට ඇදෙන ගතියකින් යුතු මැ ් ඔව බිගමනය කටනු ලැබේ..එය සමගේ ඇත්ලි වටා ඔහන විට කැඩෙනම් එය හොඳට ඇලෙන ගතියක් නැත. ඇලෙන සුළු මැටීවල ඇදෙන ගතියක් ඇත්තේ එය හොඳ මිළුනයක් හා දුනා කුඩා අංශු සිබෙන හියාය. ඇදෙන සුව මැටීවල යුතා කුඩා මැටී අංශු ඇත. නමුත් ශූතා හොඳ මැටීවල බොහෝ දුරට ඇලෙස ගඩ්යසින් හා වැඩට පහසුය.






අපි වෙනස් වෙනස් මැටිගෙන වැඩ කරන වලං සාදන ලිප් සදිහා එක හේතුවක් නම් මැට්වල ඇදෙන සුළ ගතිය**යි.** එය පිපිර්මක් නැතිව හැඩගන්**හිා** ගැනීමට පහසුය. ඒවා වේලෙන විටද නොපිපිරේ. මැට් එකට හොදිට තද වේ.


අදෙද සුව ගතිය මැට්වල කල්පැවැත්මටද බලපායි. ලෝකයේ බොහෝ රටවල වලං සාදුත්තර මැට් වැඩ කිටමට පුටමසති කිපයකට හෝ මාස කිපයකට පෙර මැට් අතාතබයි. චිතයේ වලං කාර්මිකයින් පෝකිලේත් තමැති මැට් වලින් වැඩ කපයි. ඒවා ඇලෙත සුප ගතියක් නැත. එම තිසා යපුත් යපුත්ගේ දරු මුයුධුටත් විසින් පාගා මැට් සුදාතම්කර තබයි.

ව්යලෙන විට මැට් වලට සිදුවන්නේ කුමක්ද?

මැට් කැබලි තැටගැන්වීමෙන් පසුව එය වේලීමට ශුඩ හරිනු ලැබේ. ඒවා වේලෙන විට අංඥවල තිබෙන බොහෝ පලය එනසට හුමාල වේ. මෙය සිදුවන්නේ පෙදි වේලෙන ආකාරයටය. මෙය වානය යනුසුම් අවස්ථාවල හා ද්වීව සැර අවස්ථාවල ශුක්මයින් සිදුවේ.කෙසේ හෝ මැට් කැබල් ඒවායේ පැත්තෙන් පැත්තට ව්යලමට අවශා ශුභල සිට පහලටක් විටත සහ ඇතුලත පලය හුමාලය වන නිසා ව්යලෙන වීට හැකිලීමක් ව්ය යුතුය. මැට් අංශු ශුතා කිරිටුව සිබෙන නිසා මෙය සිදුවේ. වලදේ හෝ ලිස්ම

එක කොටසක් අනෙක් කොටසට වඩා ශුක්මතට වියලෙන විට එහි අත් කොටස් පිපිර්මට පටත් ගති.ගතකළ තැබ් කොටස් සා ගත කොටස් වලට වඩා ශුක්මඩින් වියලේ.එම තිසා සෑම කොටසන්ම එකළු ගතකමකින් තිබීම වැදගත්ය. ඒවාසේ අයිත තරමක් ගතකමට තිබීය යුත්තේ එය ශූක්ෂඩින් වියෙලෙත **නි**සාය.







පාරම්පරික් භාත්මවල ගනකම අධිතකින් පෙන්නුම් කරයි.

පාරම්පරික වලත් සාදක්තත් ඒවා ව්යලීමට පහසු වීමට සාමාතා යෙත් වෙතත් දූවායත් එම මැටි වළට එක් කරයි. සාමාතා යෙත් වීශාල වැලි කැට මයිකා හෝ ව්යළුතු මැටි ( පිලිස්සුතු කැබලි අඹරා ) මිනි කල විට ඒවා හැකිලෙන්නේ තැත. ඒවා අංශු අතර ජලය රදා පවතික ජලය පිට වීමට උදව් වේ. එසේම හුමාලය වී ඉවත් වීමටද උපකාරි වේ. මෙම ශතා කුඩා සිදුරු පොරෝසිට් යනුවෙන් හැදින්වේ. ස්පත්වී එකක් මෙයට හොද තිදසුකකි. ශුතිා හොද ඇලෙන සුතු මැටි වුවද ඒවා හොදට පුවේසම් සහිතව වේලුවේ තැත්කම් පිපිරීමට ශුඩ ඇත.

DiG. ( ( ....)

පිලිස්සු මැටි කුඩු කර සාදා ගත් මැටී. මධ්කා. මෘදුකෑට තුබි පතුරු, තුබි කැබලී.





ඇත්ත වශයෙන්ම මැටි වියලෙන අවස්ථාවේද එය යුතා සොදට ශක්තිමත් වේ. තොදට ව්යල්මේන් හෝ යුතාමත් තෙනට කිබීමෙන් ඒවා නැවත හැඩ^ගැන්වීමට අමාරුය. මැටි හොදට වේලුතාට පසුව . ඒවා පහසුවෙන් නැබලි වලට කැඩෙන්නේ ඒවායේ ඇති තරම් වතුර ඒවා සවි වීමට නැති නිසාය. මැටි පිලිස්සුවාට පසුව සිදු වන්නේ කුමන්ද?.

මැට් පිලිස්ස්ම කරන වීට එය පිලිස්සුනු මැට් බවට පත් වේ. හරියාකාර පිලිස්සිමෙන් පසුව ඒවා තැපත මැට් බවට පත් කිරීමට බැරිය. මෙම මැට් පිලිස්සීමේදී ශූතාමත් අවධානය යොමු කළ යුතු පියවරවල් බිපයන් ඇත.

සො. ශ්රීට 1004 වැටි වල ජලය උතුරයි. සො. ගු. 1001–2001 ජලය ශුතා කුඩා අංශු වලි.ත් ශුවත් වේ. පලය හුමාලය ඔවට පත් වන විට එය විශාල වේ. එම නිසා පුලුස්සන පලමු වියවර වලදි ශුතා සියුම්ව කල යුතු වන්නේ එහි ඇතුලට නැවත ජලය නොයන පරිදි පිලිස්සීමය. මෙම හුමාලය කුඩා පිහිටීම් වලට හේතු වීමට ශුඩ ඇත.


සෙ. ගු. 573' ද වස මැට් හෝ සෙරමින් නොවන තත්ත්වයට පත් වේ. සිලිකාවල ඇති නිදහස් කියාව නිසා මෙස පලල් වීමට ඉඩ තිබේ. සෙ. ගු. 573' පහල මෙම සිලිකා හිරිවැටෙන තත්ත්වයට පත් වේ. සෙ. ගු. 573' ද ඒවා හදිසියේම 1% කින් විශාල වේ. එය සෙ. ගු. 573' පහලට සිතල වනතෙක් පවතී. මෙෂ්ඨ හදිසියෙන් හිරි වැටුනු තත්ත්වයට පත් වුනු විට 1% කින් හැකිලේ. එම ආකාරයෙන්ම තුනි නොවස් ඉක්මනට වේලේ. එම නිසා පිලිස්සීමේද් මෙහිද ගැටහු ඇති වීමට පිලිවත. මෙම මැට් පිලිස්සුනු තත්ත්වයට පත් වන විට පෝරනුවේ තත්ත්වය නුමානුසුල විට යුතුය. මත්ද බස් භාත්යයේ සෑම නොවසක්ම වනම වේලාවේද් සෙ. ගු. 573' ද උෂ්නත්මයට පත් විය යුතුය. මයේ නොමැති නම් වහි තුනි නොවස් ඉක්මනට පිපිරේ.

උෂ්තත්වය සෙ. හුෙ. 600 ~ 700 ත් අතර වන විට මැටි තව දුරටත් පලයෙහි දිය කල තොහැක. ඇත්තවශයෙන්ම ඒවා තව දුරටත් මැටි බොවේ. ඒවා දැක් පිළිස්ස් ඇත. එහෙත් ගෞද තත්ත්වයට පත්වීමට තව පියවරවල් කිපයක් ඇත. එය දැන් ව්යළුනු ඒවාට වඩා ශක්තියෙන් අඩුය.

යෙ. ගු. පිරිට' – 950' අතර සිටීර අංශු සින්ටර් බවට පත් වේ. මෙම නොටස් සෙරමික් ශක්තිමත් වීමට උපතාරී වේ. මෙම අංශු සිටීරට තිබෙන අතර එහි මතුපිට උනුවීම සිදු වේ. යකඩ කෑබලි උනු නොකොට එකට සවී කරන්නාක් මෙන් මැට් වල වෙනත් ඛනිජ පොටෑසියම් හෝ යනවද ඒවා සින්ටර් වීමට උපකාරී වේ. මෙයට පසුව මෙම කොටස් වෙන් කල කොහැක. නමුස් එකක් බවට පත් වී ඇත.


කෙ. ගු. 950' දී එම සෙරමික් උනු වීමට පවත් ගති. ඒවා වීදුරු සත්ත්වයට පත් වේ. වීදුරු මෙත් ඒවා ලිප් විලව නුසුදුසුය. අංශු උනු වී සිදුරු සියල්ලම වැසේ. ( ශුතා සඳව පෙරමික් හැකි ලී ඒවා උනුවේ. ) ලිප කෑම පිසිමට පුයෝජනයට ගත්තා වීට උනුසුම රදා පවතින කොටස් ශුස්මතට පලල් වේ. සෙ. ගු. 900' පහල තත්ත්වයට පිලිස්සු ලිප් වල සිදුරු පලය උරා ගැබීමට ගැනි තත්ත්ව යට පත් වත්තේ ඒවා අතර කිබෙත්තා වූ ශුතා කුඩා අංශු අතර ශුඩ තිසයි. ශුතාමත් සඳව පිලිස්සුව සෙරමික් වල පලල් වීමත් ඇති තෙවෙන නිසා එහි පිපිරීම් ඇති වීමට ශුව තිබේ.

4.




# WORKING WITH POTTERS ON STOVES

# Selecting Your Potter



- 1. High quality work. Pots that are
  - a) symmetrical;
  - b) having even thickness;
  - c) without cracks;
  - d) well fired, with even color and a good ringing sound.
- 2. Good location for clay and distribution. This is essential for avoiding delays and having access to markets.
- 3. Efficient production. You want a potter who
  - a) works hard;
  - b) works full time;
  - c) has enough work and storage space for drying large numbers of stoves;
  - d) uses a pottery wheel.
- 4. Willingness to learn and try new things.
- 5. If a potter is also willing to teach, s/he will be of great value in training other potters.



In training a potter, you must be respectful, patient, and persistent. To achieve good quality pottery stove liners, the potter must be careful in clay preparation, forming, and handling the liners while they are moist — much more careful than in making traditional pots.

Each potter has his/her own way of working. There are usually good reasons for the habits they have. Thus you should only try to change their habits when there is a particular problem caused by the habit.

# Method:

In the beginning, bring a top quality liner with you. The potter will learn most of his/her lessons from this example. Leave the liner with the potter, and order one (1) liner exactly like it. Let the potter make the stove without any instructions or templates.

When it has been fired, measure the dimensions and assess the quality. Discuss with the potter the differences between his or her stove and the sample you brought.

Then order five (5) more stoves. This time, work closely with the potter, giving instructions in the use of templates and careful handling. (Give the potter a set of templates.) Come back in two days and give instructions in assembling the pieces. Follow closely and avoid letting the potter make any mistakes - these soon become bad habits, difficult to change. Let the stoves be fired. Discuss their quality with the potter.

Then order ten (10) stoves. Work with the potter and encourage use of the templates and proper handling. Discuss any flaws with the potter before and after firing. If these stoves are

of good quality, order twenty (20) more. (If they are not all of acceptable quality, order only ten (10) more stove liners.) Let the potter make these without your assistance. But always select out unacceptable stoves before firing.

Increase the number of stoves you order from the potter according to the quality he is producing. For at least six (6) months, check the stoves before they are fired. Do not let the potter fire stoves that are distorted or have incorrect dimensions. This is crucial to developing the potter's discipline, and avoiding misunderstandings with him/her.

Emphasize
these
points
while
training:

Pottery liners must be made to the proper dimensions. Most potters will resist using templates - they've never needed them before, and may consider them an insult, rather than an aid, to their abilities. Many potters will only need to use the templates to measure the first fifty (50) stoves. After that they will only need to check a few stoves each day. If the stoves continue to be correct, then they can check them less often. If there are problems regarding size, the potter should use the templates more.

Cracking of pottery liners must be avoided. The main causes of cracking are weak joints when assembling and rapid, uneven drying. Many cracks may not appear until after firing or even during use - but the weakness was created in the pre-firing stages. Train potters to make strong joints where the tunnel and the door join the firebox. If cracking problems continue, insist that he score the surfaces to be joined. If cracking problems still continue, insist that s/he score and slip (put watery clay) onto the surfaces to be joined.

Distorting or misshaping the circular potholes must be avoided. The major cause of the circle becoming an owal shape is moving the firebox or the second burner onto an uneven surface to dry. The main causes of bumps on the rim are lumps in the coils or lifting the firebox from the top while it is still wet. Help the potter avoid distorting the liners by providing (or selling) the potter sturdy wooden planks that measure 14 by 14 inches. The extra size allows to dor to be added without moving the firebox.

Remember these differences: While you must respect the skills and traditions of the potter,, you must also understand the invisible science behind the traditions, to be able to introduce something as new and as different as the ceramic stove liner. There are some aspects of the pottery liners that the potter has no tradition for.

- 1. The firebox and second burner have no bottom.
  - a) The walls are much more likely to change shape if they are picked up before they are stiff enough to hold their shape (leatherhard).
  - b) Having an uneven floor surface actually helps support the traditional round bottom shapes. But uneven floors greatly distort the bottomless stove liner shapes.
- 2. Clay pieces are joined at right angles. All the traditional pots, especially the large ones, are single curved walls. The pots are made at one time, not assembled later.

- 3. The stove liner must be made to exact dimensions in order to work properly. The two parts must fit to gether, and the potholes must properly accommodate the cooking pots. The firebox and tunnel must promote good combustion and transfer of heat.
- 4. The stove liner will be subjected to much more heat stress in use than the cookpots or water jars. The liner requires more porosity and better fired strength. (The Sri Lankan clay appears to be well suited to stove liners.)

# Checkpoints:

When wet, are each of the parts the correct size and shape?

- 8" top diameter on the firebox (inside)
- 10" bottom diameter on the firebox (inside)
- 7" height of the firebox
- 2½" deep door
- · 7 height of tunnel
- 32" x 5" inside the tunnel
- 8" inside diameter of second pothole
- ½" potrest thickness

Are the tunnel, firebox, and door for each stove made at the same time? (If not, they are more likely to crack.)

Is the firebox left to stiffen in good condition, with the top perfectly round?

Are the tunnel and door joined to the firebox with a good, strong joint - so strong that if you pulled them apart, the walls would break instead of the joint?

Before firing, are the potholes perfectly round, and no cracks anywhere?

After firing, are there no cracks? Are the potholes a perfect circle? Are the dimensions the correct size?

Does the liner make a ringing sound when you tap on it?

YOU SHOULD ANSWER "YES!" TO ALL OF THE QUESTIONS ABOVE!

# Quality Control

# Problem Solving

Part of the extension worker's job is QUALITY COMTROL. Any problems with the stoves should be caught early, and a systematic approach used to illustrate the cause or causes of the problem to the potter. Only then can you guarantee the full participation of the potter in permanently correcting the production process. This involves a six (6) step process, outlined below with an example following.

- 1. Define the problem.
- 2. Observe carefully the entire production process, covering all possible causes of the problem.
- 3. Make a good guess at what actions or inactions might be causing the problem.
- 4. Talk with the potter about the possible causes. Ask the potter what s/he thinks the cause is.
- 5. Devise a test to scientifically determine and illustrate the causes of the problem. Try to prove and disprove both the potter's and your theories.
  - . Alter the production methods to avoid this problem.
    - \*!\* \*!\* \*!\* \*!\* \*!\* \*!\* \*!\* \*!\* \*!\*
- 1. Say, for example, that smoke and flames come up around the first pothole. You look closely and define the problem as being that the top of the firebox on many of the stoves is not perfectly round like the cookpots are.
- 2. You stay with the potter while he makes some stoves. You observe that the final shaping of the top of the firebox is done correctly, and they form a good round circle. You observe that the fireboxes are lifted from the planks the same day they are made and set on the clay floor. The clay floor is not perfectly level, and some of the fireboxes are no longer perfectly round after being moved to the floor.
- 3. You guess that the uneveness of the floor pushes up parts of the wall of the firebox, and picking up the liners while they are wet stretches the top out of shape. You guess that moving the firebox off the planks they are made on, while wet, changes the round top to an uneven oval shape.
- 4. You talk with the potter about the problem and the possible causes. The potter says that the deformation happens in the firing. He says that the liners fired in the bottom layer of the kiln bend due to the weight of the liners above them.
- 5. Now the biggest step: you test these ideas by making marks on the liners to identify them, and treating them differently during production. Keep careful records on paper.
  - a) Treat the first 10 liners in the usual way, lifting them from their boards the first day and setting them on the uneven floor. On each stove mark a number, 1,2,3,4, etc., up to 10. Make another 10 liners that are not lifted from their boards until they are leatherhard the door is added and the tunnel assembled without removing the firebox form the board, and the liner left to stiffen until it is firm. Mark a number on each stove: 11,12,13, 14, etc., up to 20.

- b) Be present during the days the liners stiffen and dry.

  Make sure the stoves numbered 11 through 20 dry to the
  leatherhard state on their boards. On a sheet of paper,
  with numbers 1 through 20 on it, write how each stove was
  treated and any observations regarding how round or how
  deformed the top of the firebox is at each stage. Record
  the dates of your observations as well as the dates of
  construction and assembly.
- c) Be present when the potter is ready to load his kiln. Be sure to mark on your paper any stoves which are already deformed. Are stoves I 10 more deformed than stoves II 20? Discuss your observations with the potter. If the stoves I 10 are significantly deformed, and stoves II -20 are not, and the potter agrees that picking them up off their boards while wet deforms them, then it is not necessary to fire the deformed ones. Have the potter place half of the I 10 stoves to be fired on the bottom layer of the kiln, and half on the top layers. Have the potter place half of the II 20 stoves on the bottom layer, and the other half on the top. Be sure to mark on your paper next to each number whether that stove was rejected, placed on the bottom layer in the kiln, or placed on the top, or middle layers of the kiln.
- d) He present when the potter unloads the kiln. Discuss with the potter the condition of the stoves. Did any of the 11 - 20 stoves fired on the bottom layer of the kiln get deformed into an oval shape? Mark the paper. Is there any difference between the I - 10 bottom layer stoves and the 11-20 bottom layer stoves? Small deformations may increase under the weight in the kiln, but a careful study would have to be done to prove this. Of the 11 - 20 stoves, are the ones placed on the bottom consistently more deformed than the ones placed in the top layers of the kiln? If so, then placement in the kiln is a cause of the problem. If not, then the potter should understand that that kiln placement is not a cause of the problem. Are the I - IO stoves consistently more deformed than the 11 - 20 stoves? If so, then keeping the wet clay firebox on its board until it is leatherhard is important in eliminating the problem of deformation. Analyse the test results with the potter.
- 6. Alter production to eliminate the problem. If the movement of wet fireboxes proved to cause deformation, then you must alter methods to enforce that the fireboxes stay on their boards from coiling to assembly to leatherhard state. If the kiln placement is (also) a problem, then production costs will rise considerably. Either the potter only fires them on the top layer in the kiln (reducing the number of stoves he can produce) or, he fires only one or two layers of stoves at a time, increasing the time and fuelwood spent on each liner.

# Other Issues

Altering the clay mix: Changing the potter's clay is possibly a solution to the problem of cracking. But it should only be tried after all other options have failed to solve the problem. Try first a) improving the joints between pieces and coils;

b) careful firing and cooling;
c) very careful handling of wet and dry liners.

It is very difficult to select clay mixes. If you continue to have cracking problems, you may require some heat-resistant material with large particle sizes to be added to the clay: either sand, mica, or grog (crushed pottery). Make sure that what you add is clean and free of salt, (ocean sand must be washed), and free of dust-sized particles, as these will reduce plasticitly without helping your cracking problem.

A 20% (twenty percent) proportion of sand, mica, or grog is usual for clay used in stoves.


Kilms and firing methods: The firing techniques in Sri lanka are quite good. Changing firing techniques is extremely difficult. If many stoves are poorly fired, the potter may be taking shortcuts to save fuelwood or time. Hefore buying any stove liner, tap on it with your finger. Listen for a good ringing sound - on all parts of the stove. This indicates it was evenly fired to a high enough temperature. If you instead hear a dull "thud" sound, then do not buy the liner. Insist that it be refired. This is an essential part of quality control. If proper firing of liners is not important to you, it will cease to be important to the potter.


Money: You must make money arrangements with the potter before you begin to work. During the training period, the potter will be spending alot of time learning how to make proper liners. Settle with him/her in advance how you will pay for this time; how many rupees for a perfect stove, how many for an imperfect stove, how many rupees, if any, for a rejected stove. Once out of the early training period, however, you should only buy the high-quality liners. Settle on a price that is fair: that encourages the potter to make liners, but not much more than s/he makes with other pottery. Keep agreements clear, quality control strict and consistent, and communication constant. Remember that making perfect liners requires boards for each firebox for about 4 days (depending on weather conditions) and more storage space than traditional pottery requires. A cost analysis (for twenty (20) stove liners) follows:


~ clay	landowner digging labour transport mixing labour water	. 30 10 20 米 <sup>25</sup> -50
- forming	labour: making coils  making pieces assembly skill training time	100
	space forwork, storage, and boards	3
-firing	firewood time and skill, firing kiln building, maintainance	. 50 75 40 355•50


Rs. 355.50 \$ 20 stoves = Rs. 17.7 each, or about 18. (It should be noted that transportation cost of clay will vary from potter to potter, and the marketing system used will affect the final price of the stove liner.


# GETTING THE MEASUREMENTS RIGHT











### OBSERVATION SHEET

Inches Too big or too small?

Effect

Height of fire box	ł	1				
Diameter of Fire box						
Height of door	•					
width of door				İ		
Depth of door						
Size of air hole				į		
Distance of air hole from ground		and the Property of the Proper				
Distance between pot holes						
Diameter of Second Pot						
Height of Pot supports				ĺ		
	1	į				
First						
FirstSecondIs the tunnel attached to						
Second	the second	i pot hole we	ll? What is	the prol	blem	
Second  Is the tunnel attached to	the second	i pot hole we	11? What is	the prol	blem	
Second  Is the tunnel attached to	the second	d pot hole we	11? What is	the prol	blem	
Second  Is the tunnel attached to	the second	i pot hole we	11? What is	the prol	blem	
Second  Is the tunnel attached to  Is the soil mix on the st  What happens if it is too	the second	i pot hole we	11? What is	the prol	blem	
Second  Is the tunnel attached to  Is the soil mix on the st  What happens if it is too	the second	i pot hole we	11? What is	the prol	blem	
Second  Is the tunnel attached to  Is the soil mix on the st  What happens if it is too	the second	i pot hole we	11? What is	the prol	blem	

# ලිප් පරීක්ෂාකරන ආකෘති පතුය.

9	<u>කල්.</u>	ූත්	වසාල	ത്രൂ	ශුතා	තුඩා .	පුතිඵලය .
ගිනි දැල් වෙන ස්ථානයේ උස <b>.</b>							
ලිට් සිදුලේ මුදුනන වීෂ්කම්ගය.							
දර දමන කවුටටේ උස.							
දර දමක කඩුක්වේ පලල.							
වා කවුරුවේ විශාලත්වය.							
බීම සිට <b>වා කවුළුවට දුර පුමා</b> කය	).						·
පලමු භාජනයට දෙවෙනි භාජනයේ 	් සිට දුර			_			
දෙවෙකි සිදුරේ විෂ්කම්ත <sub>ය</sub> .	 						
වලද ආදාරක වල උස.							
						خلق بيون ولك على حرب ولي	\$0° the Cale CE
ලිප් සිදුරු වචකුරුද? පුටීවලය කු	ලික්ද?						
පලමු වැක්ක	• • • • • •	• • • •	••••		• • • •	• • • • • • •	
දෙවැන්න	• • • • • • •	• • • •	• • • • •	•••	• • • •	• • • • • •	
වීංගෙය දෙවැන් ලිර <b>ී ස්දු</b> රට හො	දට සුව වී	ත්බේ	දී? පු	<b>්</b> තය	ූ මත් ර	<b>4</b> ?	
**************		••••	• • • •	• • • •		• • • • • •	
ලිප් මුදුනන මැටී මිශුකය මෘදුද් <b>–</b> න	දෙද? ඔව්.	තැ	۵۲ <b>-</b>				•.
එය <sub>දෙ</sub> තා මෘදු තම් කුමත් සිදු වේ				<b></b> .	. <b></b>		
							<i></i>
මෙම ලිප පිලිබඳව යොකේ පු <mark>ශ්</mark> ෂ							
	<b>J</b>		•				•

#### APPENDIX 6

#### FOLLOW UP

### INTRODUCTION

### What we mean by "Follow-Up"

Follow up means checking on progress and problems of people you have trained. Even a test at school is a type of follow up; your teacher is checking on your progress and problems.

### Why do Follow-Up?

- To help people in the field. When you check on potters and installers your first concern is to help them do a better job. Often people will not tell the installer of problems beacuse of politeness or not knowing that their stove could be better. Always be thinking of how to help people do their jobs more easily and higher quality.
- 2. To get information back to trainers and planners

You will look for problems which could be solved by better training, or a different approach. Is the installer working in too large an area? Are the installers trained to tell the women to maintain their stoves? By doing follow up you can make sure that the system is working all the way to getting stoves into houses.

3. When to do follow up.

You should check in the field <u>before</u> small problems become large problems. For installers after they have installed 10 or 20 stoves you should check on quality. If there are important mistakes the installer should be instructed immediately. Of course, any poor quality stoves should be fixed or replaced.

After solving early problems you should check on the installer after 3-6 months to assure that quality is still high, and correct any bad habits.

Followup · Lecture Notes Sinhalese version

# අනුගමනිය වැඩපිට්වෙල හැඳින්වීම

# අනුගමනය වැඩපිළිවෙල යනුවෙන් අප අදහස් කරනුයේ කුමක්ද?

අනුගමනය වැඩපිරිවෙල යනුවෙන් අදහසු කරනුයේ පුගවිය සහ සහ විසින් පුහුවු කරනු ලැබූවන්ගේ ගැටව පටිසාකර බැලීමය. පාසලන්දී කරනු ලබන පටිසාවන් වුවද එක්තරා වර්ගයක අනුගමනිය වැඩපිරිවෙලකි. සමගේ ගුදාවරයා විසින් සමගේ පුගනිය හා ගැටව පරිණා කරයි.

අනුගමනය වැඩපිට්ටෙලන් අවශා වන්නේ ඇයි?-

# l - ඉසනුයේදී චීතියුත්ව උදර් කිරීමට.

සම ලිප් සාදන්නත් සහ ඒවා සවිකරන්නත් පරිසා කිරීමේදී පමණේ පුණන අවධානය යොමුවිය යුත්තේ සවුත්ව හොඳ ලිපක් සෑදීමට උදව් තිරමටය. නොහෝට්ට මිතිසුන් සමුත්ගේ පුණිත ලිප් සවි කරන්නත්ව සමුත්ගේ හොඳගින පවත්වා ගැනීමට හෝ සමුත්ගේ ලිප හොඳට ඕයාකාරී වේය යන්න ගැන නොදනම නිසා එම පුක්ත කමට අකමැති වේ. නිතරම වාගේ මිතිසුන්ට යනුගේ පැඩය මොහෝ පහසුවට හා යුතා හොඳ තත්වයෙන් නිමා කිරීමට උදව් කරන්නේ කෙසේද යන්න ගැන සිතා බැලිය යුතුය.

# 2. පුහුපු කරන්නන්ට සහ සැලසුම් කරන්නන්ට ආපසු භෞරතුරු ලබා ගැනීම: -

ඔබ හොඳ පුහුපුවකින් හෝ වෙනන් කුළායකින් විසඳා මැලීමට ඇති ගැටට ගැන මලා පොපොඩාර්ටු විසිදු වේ. ලිප් සවි කරන්නා විශාල පුදේශයක ලිප් සවි කිරීමේ නියැලි සිටිදු ලිප් සවිකරන්නේ ගෘහම්යන්ට සවුන්ගේ ලිප් නඩන්තුව ගැන උපදෙස්දුමට පුහුපුව ලබා කිසේද මෙම අනුගමන්ය වැඩපිළිවෙල කුයාන්මක කිරීමේ වැඩකරන කුමය අනුව මොහෝ නිවෙස් වලට ලිප් ලබාදීමේ විශ්වාසය ඔබට ඇතිවෙනු ඇත.

# 3. සම අනුගමනය වැඩපිළිවෙල කරනුයේ කවදාද?

මබ සෙනු**සේ පරිසාකල යුත්තේ කුඩා ගැටව විශාල ගැටව** බවට පත්වීමට පුළුමයෝය. ඒවායේ සැලකිය යුතු ගැටව ඇත්තම් ඒ වහාම ලිප් සට් කරන්නාට ඇතුම්දිය යුතුය. ඇත්ත වශයෙන්ම විය යුතුව ඇත්තේ හි නුසුදුසු තත්වයෝ විදුරදි ඇති ලිප් නිවැරදිව නැවත සට් කිරීම හෝ ඒ **වෙනුවට වඩාත් හොඳ කායගීසංවතාවයකින් යුක්තව ලිපක් සට්කර** දීමය.

මුලික ගැටීව විසඳිමෙන් පසු සම විසින් ලිප් සව කරන්නා මාස ය කට හෝ මාස ම කට පසුව ඒවාසේ තත්වය තවදුරටත් උසස්ව නිවැරදිව හෝ නුසුදුසු තත්වසේ තිමේද සන්න ස්ථිරවම දැන – ගැනීම පිමිස පරිකෘකල යුතුය.

### APPENDIX 7


# STOVE INSTALLATION FOLLOW UP FORM

DATE	An extract the second	OBSERVER: _		1	NSTALLE	R:		
DATE	E OF INSTALLATION	<del> </del>	_ NUMBI	ER OF PEOPLE	COOKED	FOR _		
VILL	AGE NAME		_ FAMIL	Y NAME	-		TIME	AM PM
	OF STOVE							
LOCA	ATION (Floor, Corner,	on table?) _	<u>-</u>					_
		QUESTI	ONS TO A	ASK THE COOK				
1.	Does the Stove help	you?	yes _	NO	HOW?	·	····	
2.	What problems do you	have with t	he stove	?	•			٠.
	Lighting the fire		YES _	NO				
	Using more wood	<del></del>	Yes _	NO				
	Using all size pots		YES	NO				
	Slower than open fir	e	_yes _	NO				÷
3-	What do you use the	stove for?		All Cooking	g,		Everyth:	ing except
	tea0	nly for some	cooking	;	<del></del>	_ Not	at all	
4.	Did you collect mate	rials for the	e instal	lation?	<del></del>	YES _		NO
	Did the installer re	quest that ma	aterials	be ready? _	<del></del>	YES _		ио
5.	How much did the Sto	ve Liner and	Install	ation cost?				<del></del>
6.	Is the work done wel	l or poorly?	Why? _	•				
	•							<del></del>
7.	What were the instal	lers instruct	tions fo	r repair and	mainter	nance?		
~				•	·			<del></del>
		<del> </del>						<del></del>
8.	How often do you smea	ar the stove	?					

cont'd .....


Stove Installation Follow Up Form (cont'd)

9.	Do you Buy and /or Gather firewood? How many times is wood gathered per week? How many Rupees per week do you spend on firewood?
10.	Other comments from the cook
	OBSERVATIONS
1.	Is the stove warm?YESNO
2.	Is the stove kept clear of ashes? YES NO  Is the tunnel clean? YES NO
3.	Is the stove well cared for? Is it well smeared?
4.	Is the stove in a good location?
5.	Is the second pot hole correctly positioned?
6.	Is the secondary air hole correctly positioned?
7.	Is the mix covering the liner well smoothed and shaped?
8.	Does the mix crumbel when you rub your thumb on it? YES NO WHY?
9.	Point out where any cracks or problems are on the stove.



	ිද <u>් සැකසීමේ ඇගයිව් පිලිබඳ පති</u> කාව.
	දිනය
	ලිපු සතුස් කල දිනය
	ගුවේ නම
,	
	ලිප සාදා ඇති ස්ථානය.( බීම. මුල්ලක.උස් ස්ථානය.(පෝරනුවක)
	ගුනුත්ත ගෙන් ඇසිය යුතු පුෂ්ණ •
	ା. මෙම ලිප සබව පුයෝපනවත්ද? සවී නැත කෙසේද
	2. ලිප පාවිච්චයේදී ඇයි බාධක චොතවාද?
	ගිනි දැල්වීමේදී. ඔව් නැත
	දර වැඩිපුර වැය වේද? ඔව් නැත
	සෑම පුමාකයකම භාජන පාව්වීව් කරනවාද?   සව් නැත නැත
	පාරම්පරික ලිපට වඩා වැඩි වේලාවක් ගත වේද? ඔව් නැත කැත
	ී.ලිප පාවිච්චි කරණ ආකාරය.−සියළුම කෑම පිසිම Æදහා <b> </b>
	–සියළුම කෑම වුල්ග පිසීමට (හේ හැර)
	– ආහාර ව <b>්</b> ග කිපයක් පිසිම සදහා
	– පාවිච්චි නොකරණ
•	4.ලිප සකස් කිරීමට ම්ශුණයට අවශා දුවා ඔබ එකතු කලාද? ඔව් නැත නැත
	ලිප සකස් කරන්නා අවශා දෑ රැස්බ්රිමට
	5.ලිප සකස් කිරීම සඳහා සම්පූර්ක ව්යදම
	6.ලිප සවී කිරීම සිදු වූ අයුරු. සාර්ථක ලෙසද? අසාර්ථක ලෙසද? එසේ තම් හේතු
	7 2 3 3 5 7 2 2 - 3 - 3 - 3 - 3 - 3 - 3 - 3 - 3
	7.ලිප අවත් වැඩියා කිරීම සදහා දිගු කල් පැවැත්ම සදහා ලැබූ උපදෙස් කවරේද?
	8 Hours and A.S. m. a manual sola established a manufactural solation
	පිංළිපෙහි ගොම මැටි ගෑම කරනුයේ කවර අන්දමකින්ද? උදා දෙසහියකට වරක් මාසිකව
•	9-දුර ලබා ගන්නා ආකාරය.–ම්ලදී ගැනීම.ඔව් තැන
	-සපියතට අර සඳහා වැන කරන වුදල
	— მოგ ობ თოვ? ლე თლი — მ
	– සහිධකට කි වතාවක්ද
	10.ලිප පිලිබඳව ගෘහතියගේ අදහස් සහ යෝජනා
	•••••••••••••••••••••••••••••
	ලිප පරීක්ෂා කිරීම.
•	l . දුිපේ ස්වතාවය . උනුදිසුම්ව ඇත නැත
	2. ලිපෙම් අව පිරි ඇත තැත
į	යි. බ්•ගෙය පිරිසිදුව ඇත කැත
	4. ලිපෙහි පවතින ස්වභාවය මකසේද?
	ලිග පිරිසිදුව තබා ගන්නේද? සව් නැත
	5. ලීප සාදා ඇති ස්ථානය සුදුසුද? නුසුදුසුද?
	and the control of th

6.	ිදෙවන භාපනය පාට්ට්ට් නිරීමට ලිප් සිදුර නිවරදිව සකසා නිබේද?
7.	වා කවුළුව ම්වරදිව සකසා පිබේද?
	ලිපෙති කිමාව. ( තැඩ තැන්වීම.සහ මැදීම සඳහා ගත් වීශුනය හොදද? 
9.	ව්යුයයේ හැකිලීම් පවතිද? සව් තැත ව්ස්තර දක්වන්න
10	-ලිපෙහි පිපිරිමි සහපුශ් <b>ණ ඇති ස්ථාන රූප සටහනේ ලකු</b> කු කරන්න .



II. මේ පිලි බඳව ඔබගේ වෙතත් අදහස් සහ යෝජනා පසු පිටෙහි සදහන් කරන්න.

### QUIZ FOR FINAL DAY OF COURSE

Answer these questions:

#### NAME:

- 1. Why are we working with improved cookstoves?
- 2. What are the advantages of cooking on

An Open Fire

An Improved Cookstove

3. Name 3 problems caused by destroying Sri Lanka's forest.

4. Write in the proper wet dimensions of the stove.

5. Name 2 ways to ensure that the front pot seat is flat and round.

Ouiz for	final	day of	Course	(contid)
AUTT IOI	TTHOT	uay vi	COUL SC	(COHE U)

9일하는 이 전환 전혀 있는 얼마나라는 그네.				
6. What is	one common	fault with	the back	pot seat?

7 _	Tf	a	potter	asks	for	payment	for	badly	built.	stoves.	what.	bluow	VOII	sav?
	<b>T</b> T	<b>a</b>	horrer	aono	101	<b>halmette</b>	TOL	Dauly	DUTTE	acoves,	WIIGL	MOUTO	you	sayı

8.	List	the	materials	and	quantities	required	to	install	а	stove,	except
	liner	anı	d water.								

l.	


9. What questions should you ask a householder before installing a stove?

10. What happens if you don't use enough sand in the mix for installing?

11. Why would smoke come out of the firebox door if the second pot is high enough?

<sup>2.</sup> 

	Quiz	z for final day of Course (cont'd)
	12.	What problems are caused by non-round pot holes?
機会の を行うできない。 を行うできない。 を行うできない。 を行うできない。 を行うできない。 を行うできない。	13.	What are <u>two</u> possible causes of a slow smoky fire?
	14.	How long after training do you carry out the first follow-up of an
		installer?
	15.	If someone says they like the stove and use it all the time, what should you check?



06.	පඹේ අදහස් අනුව දෙවන භාජනය පාට්ච්ච් ක <b>ුනු ලබන ලිප් සිදු</b> රේ දැකිය හැකි පොදු වැරැද්ද තුමක්ද?
07.	
• • • •	වශයෙන් සහ නුමක් කියන්නේද?
• • •	Coloratetata efetafetatata eta etafetatata eta etata e eta era era era eta eta eta eta eta eta eta era era era
	era allatata a atutatara ata atatatatatataratarataratara arai a arai arai
•	This alphabatate planglabate electrical eferentes en energiales electricales en este este este electricales e
	•••••••••
08.	ලිපක් මැටි ගැසීමේදී ගනු ලබන දුවහයන් සහ පුමාවයන් පිළිබඳ ලැබිස්තුපක් ගනස් කරන්න.
	1
	II
	<b></b>
	lv
C9.	ලිපක් මැටී ගැසීමට පලමු ගංග මුටිකයාගෙන් යන ඇසිය යුතු මුලික කරුනු මොනොද?
	***************************************
	***************************************
10.	ිලිපත් මැටිගැසීමේදී ගත්තා ම්ලනය සදිනා පුළාසවත් කරම් වැලි පුළාදයේ පැවිවිඩි නොකිරීවේම - කුමක් වත්තේද?
	***************************************
	************************************
11.	දෙවන ලිප් සිදුර පුමාණවත් උසකින් සහ තරියාකාරව සකස්කර නිමියදී දය දමන ඔයුවලට ි දුම් පිට්වන්නේ ඇයි?
	***************************************
	***************************************
12.	තිසියාකාර හැටයක් තැයි සිදුරු සහිත ලිපත් පාරිච්චි බ්රීමේදී ඇසිවත යුශ්හ සොකථාය.
	***************************************
	***************************************
13.	ලිප පාට්ට්ට්යේදී දුම් සහිත හෙමින් ගින්ද දැල්ටේ. හේතු & ස් දුන්නේක.
	1
	11

14.	. ලිප් කියෙස්වල සටිකයන්නෙකු විධිවිදව පලමුවෙන්ම යුම සොයා මැලිය යුග්තේ පුහුසුවෙන් කොපමය කාලයකට පසුවද?
15.	ිජි පාපිච්චි කටන්නෙකු ලිපට වඩාත් කැමති ගපක් නිතරම පාච්චිචි කටන ඔවත් සඳහන් කටයි. එවිචි සම විසින් පරිඥාතල යුත්තේ තුමන්ද?
	***************************************
• • • •	
් එල්/ ර	and the second of the second o
	***************************************
	e la

### QUESTIONNAIRE FOR COURSE EVALUATION

# SARVODAYA/CEB TRAINING COURSE AUGUST 1985

This questionnaire is designed to help us plan future training courses so you honest comments will be appreciated. The answers will be used only to improve the next training course so you do not need to put your name on this paper and it will not affect your certificate for the course.

1.	How was the length of the course? (tick one)	too long
		0.K.
		too short
2.	How was the amount of work? (tick one)	too much
		O.K.
		too little
3-	How was the amount of lectures compared with	
	practical work? (tick one)	too much talking
		0.K.
		too much practical
4.	How was the amount of discussion?	too much
		0.K.
		too little
5.	The course included theory. Was it .	too much theory
		0.K.
	•	too little theory
6.	There were four main subjects to the course. Put a with which you had problems during the course.	tick by any subject
	Working with Potters	
	Installation	
	Fault Finding	
	Follow up	

		Evaluation	

7. Do you think some things were not necessary? If so, what?

8. Do you think some things should be added or more time spent on them? If so, what?

9. Say how you think the course can be improved.

# Questionmaire for course Evaluation – Binhales e 46 ਪ੍ਰਤੀ පිළිබඳ පාඨමාලාව – 1985 අගෝස්තු යුත්ථන පිරිමැස්මේ දර උඳුන් පිළිබඳ පාඨමාලාව – 1985 අගෝස්තු සර්වෝදය ශී.ලං.වී.ම. (බලශක්ති ඒකනය) හා ඒකාබද්ධව

පාඨමාලා ඇගයම: –

09.

මෙම ඇගයිම් පසුිකාවෙන් අප බලාපොරොන්තු වන්නේ අපගේ ශුදිරි වැඩසටහන් පුමවත් කපගැනීම බැවීන් පාඨමාලා ලාහන්ගේ අවංක අදහස් සහ යෝජනා ශූතාමන් අගේකොට සලකමු. පුබගේ පිටිතුරු හැබවීන්ම අප ලබා ගනුයේ ශුදිරි වැඩකටයුතු සාර්ථක කපගැනීම ස්දහා පමණි. එබැවීන් සබගේ නම සඳහන් කිරීම අවශා නැත. පාඨමාලාව සහ සහතික පතු බෙදාදම පිරිබඳව මෙහි කිසිඳු සම්බන්ධයක් නැත.

සපශනු	പ്പത് മുതം	
		<u>කාලය විතාව 30 සි (ඉදිරියේ ඇති කොටුවේ හමාගේ තැමැත්</u>
01.	පාඨමාලා කාලය	☐ ශුතාවක් වැඩිය. අනුව 🖈 ලකුණ යොදක්ක)
		🔲 පුමානවත්ය.
02.	පෘථමාලාවේ <mark>වැඩ</mark> කුල පුමානය	🔲 ශූතාමත් කෙවීය. 🔲 ශූතාමත් වැධිය.
	2,20,0,00 ptm@C 32,200	
		🔲 පුළාණවත්ය.
		🗖 පුමානවත් තොවේ.
03.	දේශන <mark>හා සංසන්දාය නි</mark> රීමේදී	
	පුංයේම්ත වැඩසටහන්සල	🗖 දේශත වැඩියි.
	<u>ට්</u> යාපත	🔲 පුමාංධවේ.
		🔲 පුාපෝගික පුරු වැසිටී.
O4.	සායාවීමා කල කෘලය	🗖 ශුතාවක් පැඩිසි.
		🗖 ರಲಾಪರಿಶ.
		🗖 පුමාසවත් තොවේ.
05.	<b>පා</b> ටමාලාවේ <mark>න</mark> හැධින දැනුම	🗖 ඉතාමත් වැඩියි.
		<b>ට</b> පුමාණවත්.
		🛘 පුමාණවස් තොවේ.
06.	පායමාලාවේ විෂයයන් 4 ක් තිබුකි.	ඉත් ඔබට පුණ්ත ඇති විසයයන් කටි ∨ ්⊃ැනින් පොල්ටන්න.
		🗖 වලං කාර්මිකුධින් සමග වැඩ ශිල්ම.
		🖸 ලීප් සැකස්ම. (මැට් ගැබීම)
		🗖 දිජවල වැරදි ලකු පිරිලි.
		🔲 අනුගමනය වැඩපිරිපෙල.
07.	ප <b>ාමාලාව වි</b> ෂයට අ <b>ුනල නොවන</b>	ා අ <mark>තවශා , කොටත් ති</mark> මුතේද <i>ී</i> එසේනම් ඒ පොසදාද <i>ී</i>
08.	පායමාදුවේ පැඩිපුර කාලය <mark>න් ගෙන</mark> එසේන <b>ම්</b> ඒ වොතවාද?	ා <b>යාකච්ථා කලයුතු පත අදහස් ඇක්වි</b> ය යුතු යෝටස් සියුදුයේදා.

වියට වාලාව පාර්ගත කරගැනීමට සමේ අවස් අදහස් හා ධෝජනා දක්වන්න.

## Appendix 10

# Compilation of Trainees' Evaluation Sheets

## Sri Lanka Training - Aug. 1985

Question	Number of Peor	ole Giving	These Responses
	Too Much	Enough	Too Little
1. Total time of training ?	o	9	2
2. Total amount of work ?	<b>o</b>	10	1
3. Too much theory ? (over practical)	4	7	0
4. Time for discussion	n ? 0	6	5
5. Information present on theory ?	ted O	8	3

6.	Which subjects were the working with potters	re 4	problems with?
	installing	3	(one person indicated
	troubleshooting	2	
	followup	2	-
	none	3	

## Essay questions

- 7. Were there any unnecessary parts of the training? Which?
  - \* Sometimes the lectures would go off the topic; sometimes the lectures didn't finish. (4)
  - \* No unnecessary parts. All subjects important. (4)
  - \* Sometimes too much time spent on examples, thus we lost our attention. (1)

8. Were there parts which needed more time spent on	them?
* Firing of pottery liners, kiln placement	(3)
* Practice making pottery liners	(3)
* Production of pottery liner	(2)
* Scientific details of combustion, fire, fuels	
* Training well organised, lectures okay	(2)
* Followup ideas	(1)
<ul><li>* Selection of, and mixing, pottery clay</li><li>* Installation materials, working with clay</li></ul>	(1)
from many areas	(1)
* Doing cooking tests, in the field	(1)
* Use and maintainance of stoves for housewives	(1)
* General need for more discussion	(1)
9. What are your ideas on how to make future training succeed?	gs
* Include more practical experience, especially	
in making the pottery liners, mixing clay,	
and loading the kiln	(5)
* Include more group discussion	(5)
* More free time in evenings to study, exchange	• - •
ideas	(3)
* Better translation	(2)
* Quieter environment	(2)
* Select trainees with common knowledge, and	
look at trainees' personal character	(1)
* Shouldn't force people to go to Family	<b>(3.</b> )
Gatherings	(1)